



Seismic Behavior of Curved Bridge in Mountain Area

Shuichi Fujikura

Nguyen Minh Hai

Associate Professor

Engineer

Assistant Professor

Utsunomiva University

Chodai Co.,LTD

Utsunomiva University

Utsunomiya, Japan

Tokyo, Japan

Utsunomiya, Japan

shuichi.fujikura@cc.utsunomiya-u.ac.jp sakakibara-y@chodai.co.jp

Yuji Sakakibara

nguyenminhhai@cc.utsunomiya-u.ac.jp

Akinori Nakajima

Professor

Utsunomiya University

Utsunomiya, Japan

akinorin@cc.utsunomiya-u.ac.jp

Contact: shuichi.fujikura@cc.utsunomiya-u.ac.jp

1 Abstract

The 2016 Kumamoto Earthquake occurred in central Kyushu, Japan, on April 14th with Mw 6.2 followed by the Mw 7.0 mainshock on April 16th. These earthquakes were mainly caused by the Futagawa fault and Hinagu fault where surface ruptures extended about 34 km long. Some of the bridges located in mountain area and close to the fault were damaged due to these near-field earthquakes. Oginosaka Bridge is one of them and is a horizontally curved bridge with longitudinal and transverse slope, which is a feature of the bridges located in mountain area. The superstructure was rotated on plan and displaced transversely at both abutments to the opposite side, and there was an evidence of the deck-abutment pounding in longitudinal direction. In order to investigate the seismic behavior of the curved bridge, nonlinear time-history analyses including a deck-abutment pounding interaction were carried out. The deck-abutment pounding interaction considered in the analyses could capture the post-impact response of the superstructure. The near-field ground motions were used for the analyses. The analytical results showed that the curved bridge is susceptible to the deck rotation caused by pounding in longitudinal direction at the deck end under earthquake loading.

Keywords: Curved Bridge, Near-field Earthquake, Seismic Behavior, Nonlinear time history analyses

2 Introduction

The 2016 Kumamoto Earthquake occurred in central Kyushu, Japan, on April 14th with Mw 6.2 followed by the Mw 7.0 mainshock on April 16th. These earthquakes were mainly caused by the Futagawa fault and Hinagu fault where surface ruptures extended about 34 km long. Some of the bridges located in mountain area and close to the fault were damaged due to these near-field earthquakes. Oginosaka Bridge is one of them and is a horizontally curved bridge with longitudinal and transverse slope, which is a feature of the bridges located in mountain area [1]. The superstructure was rotated on plan and displaced transversely at both abutments to the opposite side, and there was an evidence of the deck-abutment pounding in longitudinal direction.

The rotation of the horizontally curved earthquake has been also observed in the previous earthquakes. Therefore, in order to investigate the seismic behavior of the curved bridge, nonlinear timehistory analyses including a deck-abutment pounding interaction were carried out. The deck-